

SeRFIn Seismic Retrofitting of RC Frames with RC Infilling



RC Infilling of Existing RC Structures for Seismic Retrofitting

C. Z. Chrysostomou, N. Kyriakides, P. Kotronis, P. Roussis, M. Poljansek, F. Taucer


Seismic Retrofitting of RC Frames with RC Infilling (SERFIN) Partners

- Cyprus University of Technology
 - C. Z. Chrysostomou (coordinator),
N. Kyriakides
- University of Cyprus
 - P. Roussis
- University of Nantes, France
 - P. Kotronis
- DENCO, Greece
 - T. Panagiotakos, A. Kosmopoulos

- Prof. Michael Fardis for his invaluable suggestions for the setting-up of the mock-up and testing campaign
- Artur Pinto, Georges Magonette, Francisco Javier Molina, Fabio Taucer, Martin Poljansek and all the personnel of the ELSA laboratory for their contribution in building and testing the structure

Statement of the problem

- Large number of structures designed without seismic design provisions
- Multi-storey reinforced concrete buildings can be most effectively and economically retrofitted by the construction of new walls



Original Frame




Retrofitted Frame


- Percentage of the reinforcement in the RC infill
 - different percentages of infill wall reinforcement have been studied
- Connection between the RC infill and the surrounding RC frame
 - two types of connection between the infill and the bounding frame (epoxy grouted dowels and/or wall reinforcement starter bars)

SeRFIn *Fulfillment of objectives through a testing campaign*

- Test a structure (consisting of two parallel retrofitted RC frames) using the pseudo-dynamic method
- The frame corresponds to frames designed for gravity-loads only in the 1970's



Elevation of test structure




Perspective of mock-up

- The proposed structure represents typical construction of the late 70's and beginning of the 80's in Cyprus
- Structures at that time were designed for gravity loads only, since there were no provisions for earthquake loading
- Use the provisions of BS8110 which is very close to those of CP110 with very minor differences
- Reinforcement details used for the design were according to CP110:1972 and BS8110:1983


Design of frame: Prototype structure

- 4 frames
- Columns
 - 25cmx40cm
 - Long dim. along plane of loading
- Beams
 - 25cmx50cm
- Slab
 - 15cm thick



SeRFIn *Design of frame: Mock-up without infills*

- 2 end-frames of the prototype structure
- Columns
 - 25cmx40cm
 - Long dim. along plane of loading
- Beams
 - 25cmx50cm
- Slab
 - 15cm thick



- Concrete:
 - C20/25 for both the frame and the walls
 - Unit weight 25 kN/m³
 - $E = 30000$ MPa
- Reinforcing steel
 - $f_{yk} = 400$ MPa ribbed bars for both bending and shear reinforcement for the frame (existing structure)
 - $f_{yk} = 450$ MPa ribbed bars for the RC infill and the dowels to be used for connecting the wall to the bounding frame members

Design of frame: Loads, Load-combinations, Material factors

- The frame was designed for gravity loads only
The loads used were the following:
 - Self-weight: this was calculated using the unit weight of concrete specified above
 - Imposed dead load: 3 kN/m² including the load of infills
 - Live load: 1.5 kN/m²
- Partial factors of safety for loads
 - 1.4 for self-weight and imposed dead-load, and
 - 1.6 for live load.
- Material partial factors
 - 1.5 for concrete and
 - 1.15 for steel

Design of frame: Resulting reinforcement details



©European Commission,
JRC, ELSA



- Made of reinforced concrete
- Connected to the bounding frame by starter bars and/or dowels



- By design the dimensions are such, so as to have high aspect ratio
 - Bending dominated behaviour
 - Higher modes involved after yielding of the wall at the base
- The RC infill wall has the same thickness as the width of the frame members
 - Try to avoid
 - diagonal cracking of the wall
 - failure of the interface connection



RC infills – Parameters to be investigated



- Percentage of the reinforcement in the RC infill
 - different percentages of infill wall reinforcement was studied

story	N Wall								S Wall							
	web bars	embedment of web starter bars, mm		Φ mm	Dowels				web bars	embedment of web starter bars, mm		Φ mm	dowels			
					embedment, mm								embedment, mm			
					bottom & east in:		top&west in:						bottom & east in:		top&west in:	
		in wall	in frame		wall	frame	wall	frame		in wall	In frame		wall	frame	wall	frame
1	Φ 12@200	600	230	Φ20	160	160	600	190	Φ 10@200	500	170	Φ 20	160	160	500	160
2	Φ 10@200	500	170	Φ20	160	160	500	160	Φ 8@200	400	120	Φ18	145	145	400	145
3	Φ 8@200			Φ18	400	145	400	145	Φ 8@200			Φ16	400	130	400	130
4	Φ 8@200			Φ16	400	130	400	130	Φ 8@200			Φ16	400	130	400	130

RC infills – Parameters to be investigated


- Connection between the RC infill and the surrounding RC frame
 - epoxy grouted dowels and/or wall reinforcement starter bars
 - two cases are examined
 - Continuity of web reinforcement is provided through lap splices and dowels are provided for shear
 - Web reinforcement is placed at the phase of the bounding members and dowels are provided which double as
 - dowels
 - anchorage of the web panel to the surrounding frame but violating the 50mm or 4Φ clear distance requirement for lapping


North Wall




SERFIN Project Design of Test Frame	Scale 1:20	Drawing No. Str
	Nov. 2010	
Title: Web reinforcement and dowels		
North wall elevation		

Reinforcement Details





Dowels and starter bars



Dowels only

Pictures of construction



Pictures of construction



Pictures of construction



Pictures of construction




Strengthening of ground floor columns



Strengthening of ground floor columns





Displacement	Gefran PZ12 100	4
	Gefran PZ12 50	68
	Gefran PZ12 25	32
	Heidenhein	8
Inclination	Schaewitz AccuStar	22
Force	Piston Load Cell	8

- 3 tests were performed
 - Pseudo-dynamic testing
 - 0.10g
 - 0.25g
 - Cyclic testing
 - Displacement controlled triangular distribution
 - Actuators
 - 2 x 1000 kN at the top two floors
 - 2 x 500 kN at the bottom two floors



- The Hercegnovi transverse accelerogram was used, scaled to 0.25g





South frame
(with less reinforcement)




North frame
(with more reinforcement)










Storey-shears vs. *i*-d for 0.25 g







Storey-shears vs. i -d for 0.25 g...




Base-shear vs. top displacement for 0.25 g...




SeRFIn *Lap-splice failure – West column of North frame*




SeRFIn *Lap-splice failure – West column of South frame*



SeRFIn *Lap-splice failure – East column of South frame*





SeRFIn *Lap-splice failure – East column of South frame*





Beam cracking




© European Commission, IRC, EISA
2011-11-30




© European Commission, IRC, EISA
2011-11-30







© European Commission, JRC, ELSA
2011-11-30




© European Commission, JRC, ELSA
2011-11-30

Ground beam cracking – North wall









SERFIN ELSA [RC Building]
f21: Final cyclic test 07/12/2011
NORTH

**North frame
(with more
reinforcement)**




SERFIN ELSA [RC Building]
f21: Final cyclic test 07/12/2011
SOUTH


**South frame
(with less
reinforcement)**



SERFIN ELSA [RC Building] (82: Controller Derived)
f21: Final cyclic test 07/12/2011
Level 1



Cyclic testing



- The structure managed to sustain an earthquake of 0.25g without significant damage
- Some column lap-splices failed with concrete spalling, but the structure continued to carry load
- The 3-sided FRPs protected the wall bounding columns at the 1st floor and prevented lap-splice failure

- The “weak” frame behaved equally well as the “strong” frame
- There has not been visible movement at the interface between the wall and the bounding frame
- The behaviour of the wall was mainly flexural, although on the south-frame wall some diagonal cracks appeared

- Some vertical cracks appeared at the connection of the beams to both the exterior column and the wall columns
- A horizontal crack appeared at the ground beam of the walls, and it was the main reason for loss of strength of the south frame
- The proposed system seems to behave in a satisfactory manner

Thank you for your attention