

Introduction to Embedded Systems

EHB326E

Lectures

Prof. Dr. Müştak E. Yalçın

Istanbul Technical University

mustak.yalcin@itu.edu.tr

PICOBLAZE OVERVIEW

The PicoBlaze processor is a compact 8-bit microcontroller core for Xilinx FPGA devices.

Required Reading:

- Xilinx, "PicoBlaze 8-bit Embedded Microcontroller User Guide",
https://www.xilinx.com/support/documentation/ip_documentation/ug129.pdf  
- Pong P. Chu, "FPGA Prototyping by VHDL Examples: Xilinx Spartan -3 Version", Chapter 14, Wiley 2008, 

PicoBlaze Block Diagram

CONTROLLER





Figure 1-1: PicoBlaze Embedded Microcontroller Block Diagram

PicoBlaze:Basic organization


PicoBlaze is a compact 8-bit microcontroller:

- 8-bit data width
- 8-bit ALU with the carry and zero flags
- 16 8-bit general-purpose registers
- 64-byte data memory
- 18-bit instruction width
- 10-bit instruction address, which supports a program up to 1024 instructions
- 31-word call return stack
- 256 input ports and 256 output ports
- 2 clock cycles per instruction
- 5 clock cycles for interrupt handling

PicoBlaze:Basic organization




PicoBlaze's Registers



- sX,sY:each representing one of the 16 general-purpose registers, where X and Y take on hexadecimal values from 0 to F.
- pc: program counter.
- tos: top-of-stack pointer of the callreturn stack.
- c,z,i:carry,zero,and interrupt flags.
- KK:8-bit constant value or port id, which is usually expressed as two hexadecimal digits.
- SS: 6-bit constant data memory address, which is usually expressed as two hexadecimal digits.
- AAA: 10-bit constant instruction memory address, which is usually expressed as three hexadecimal digits.

PicoBlaze Interface Connections




- CLK(input, 1 bit): system clock signal.
- RESET (input, 1 bit): reset signal
[PC=0; Flags Cleared; Interrupts disabled; CALL/RETURN Stack reset].
- PORT_ID (output, 8 bits): address of the input or output port.
- IN_PORT (input, 8 bits): input data from I/O peripherals.
- READ_STROBE (output, 1 bit): strobe associate with the Input op.
- OUT_PORT (output, 8 bits): output data to I/O peripherals.
- WRITE_STROBE (output, 1 bit): strobe associated with the Output op.
- INTERRUPT (input, 1 bit): interrupt request from I/O peripherals.
- INTERRUPT_ACK (output, 1 bit): interrupt ackn. to peripherals.

PicoBlaze's I/O


Port Timing during an input instruction (2 clock cycles)!

INPUT sX, (sY) (IN sX, sY)	Read value on input port location pointed to by register sY into register sX	PORT_ID \leftarrow sY sX \leftarrow IN_PORT	-	-
-------------------------------	---	--	---	---



PicoBlaze's I/O: READ_STROBE


READ_STROBE Indicates a Successful INPUT Operation



PicoBlaze's I/O

Port Timing during an output instruction (2 clock cycles)!


OUTPUT sX, pp (OUT sX, pp)	Write register sX to output port location pp	PORT_ID \leftarrow pp	-	-
-------------------------------	--	-------------------------	---	---



UIC129 v5.06 080404

PicoBlaze's I/O: WRITE_STROBE

WRITE_STROBE : data on the OUT_PORT port is valid and ready for capture.



Instruction format

- op sX,sY:register-register format. $sX \leftarrow sX \text{ op } sY$
- op sX,KK:register-constant format. $sX \leftarrow sX \text{ op } KK$
- op sX: single-register format. $sX \leftarrow \text{op } sX$
- op AAA: single-address format (jump and call operations).

Instruction Set

- Arithmetic / Logical Instruction

- Logical instructions,

```
and sX,sY; // sX ← sX AND sY, c ← 0
```

```
xor sX,KK; // sX ← sX XOR KK, c ← 0
```

- Arithmetic instructions

```
add sX,sY; // sX ← sX + sY
```

```
addc sX,KK; // sX ← sX + KK + c
```

- Compare and test instructions

```
comp sX,sY; // if (sX==sY z ← 1 else z ← 0;
```

```
              if (sY>sX c ← 1 else c ← 0
```

```
test sX,sY; // t ← sX AND sY; if t=0 z ← 1 else z ← 0;
```


```
              c ← t(7)XOR t(6) ...XOR t(0)
```

- Shift and rotate instructions

```
s10 sX; // sX ← sX(0...6) & 0; c ← 0
```

Instruction Set

- Data-transfer Instructions



Instruction Set

- Data-transfer Instructions

```
load sX,KK; // sX ← KK (immediate add.)
```

```
load sX,sY; // sX ← sY (register direct add.)
```

```
fetch sX,(sY); // sX ← RAM(SS) (register indirect)
```

```
fetch sX,SS; // sX ← RAM(sY) (register indirect)
```

```
input sX,KK; // port_id ← KK, sX ← in_port
```

```
output sX,(sY); // port_id ← sY, out_port ← sX
```


Instruction Set

- Branch instructions: Program flow control instructions

jump does not affect CALL/RETURN Stack and does not affect CARRY and ZERO

call push the current PC to stack and load PC with label then executes until RETURN

ret pop the stack and increment the value then load into PC.



Instruction Set


- Branch instructions: Program flow control instructions

jump AAA; //pc \leftarrow AAA (unconditional jump)

jmpc AAA; //if (c=1) pc= \leftarrow AAA else pc=pc+1; (conditional)


call AAA; //tos=tos+1; STACK[tos] \leftarrow pc; pc \leftarrow AAA

ret c; //if(c) pc \leftarrow 1+STACK[tos]; tos=tos-1; else pc=pc+1




Instruction Set

- Branch instructions: Interrupt related instructions



!!!!Interrupt signal must be applied at least 2 clock cycles !!

Instruction Set



UG129_c4_03_051404

Instruction Set

- Branch instructions: Interrupt related instructions

```
eint; // enable interrupt
```


```
dint; // disable interrupt
```

```
reti disable; // return the interrupt and disable  
interrupt, pc ← STACK[tos]; tos=tos-1;c,  
z← preserved c, z
```

Read :Pong P. Chu, "FPGA Prototyping by VHDL Examples: Xilinx Spartan -3 Version", Chapter 14, Wiley 2008

PicoBlaze Instruction Set simulator:

► Download (1.1MB): <http://web.itu.edu.tr/yalcinmust/EHB432/PBTool02a.zip>



Programs...

```
; 24-bit addition: {x2,x1,x0}+{y2,y1,y0}
PIN00 DSIN $00
POUT00 DSOUT $00
...
PIN05 DSIN $05
POUT05 DSOUT $05

x0 EQU $00
x1 EQU $01
x2 EQU $02
y0 EQU $03
y1 EQU $04
y2 EQU $05
in s0,x0
...
in s5,y2
add s0,s3 ;add least significant bytes
addc s1,s4 ;add middle bytes with carry
addc s2,s5 ;add most sig. bytes with carry
out s2, x0
out s1, x1
out s0, x2
```

```
; bit manipulation
PIN00 DSIN $00
POUT00 DSOUT $00
PIN01 DSIN $01
POUT01 DSOUT $01
PIN02 DSIN $02
POUT02 DSOUT $02

set_mask equ $02
clr_mask equ $fd
tog_mask equ $02

in s0,$00;
or s0,set_mask ;set 2nd LSB to 1
out s0, $00
in s1,$01
and s1,clr_mask ;clear 2nd LSB to 0
out s1,$01
in s2,$02
xor s2,tog_mask ;toggle 2nd LSB
out s2,$02
```

```
if (s0==s1){  
    /* then-branch statements */  
  
    else {  
  
        /* else-branch statements */  
  
    }  
}
```

```
switch (s0) {  
  
    case value1:  
        /* case value1 statements */  
  
        break;  
    case value2:  
        /* case value2 statements */  
  
        break;  
    case value3:  
        /* case value3 statements */  
  
        break;  
    default:  
        /* default statements */  
}
```

```
compare s0, s1  
jump nz, else-branch  
;code for then branch  
...  
jump if-done  
else-branch :  
    ;code for else branch  
    ...  
if-done:  
    ;code following if statement  
    ...  
constant value1 , ...  
constant value2, ...  
  
compare s0, value1  
jump nz, case-2  
;code for case 1  
...  
jump case-done  
case-2 :  
    compare s0, value2  
    jump nz, case-3  
    ;code for case 2  
    ...  
    jump case-done  
case-3 :  
    compare S0, value3  
    jump default  
    ;code for case 3  
    jump case-done  
default:  
    ;code for default case  
    ...  
case-done :
```

```
for (i=MAX;i>0;i--) {  
...  
}
```

```
for (i=MAX;i>=0;i--) {  
...  
}
```

```
nop:  
load sX,sX
```

```
load s0, MAX  
for_loop:  
...  
sub s0,1  
jump nz, for_loop
```

```
load s0, MAX  
for_loop:  
...  
sub s0,1  
jump nc, for_loop
```